

Annexure D

BUILDING SAFETY CERTIFICATE

No. ...PWD/off/NBC/107...

Dated: ...23/09/2024...

It is certified that the existing building.....IPM SCHOOL.....(name of the building or premises) atPallavpuram, Phase-I, Meerut-250110.....

(address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
School	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	3 Floor	3 Floor				

The building is owned/occupied byIPM SCHOOL.....(name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned ofMr. Manoj Kumar, Asst. Engineer..... (Name of Department/ Govt.) on.....19/09/2024..... (date of inspection) in the presence ofMr. Vikas Verma, Secretary, IPM SCHOOL..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from...23/09/2024.....for a period of...1...year in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on.....23/09/2024.....atMeerut..... by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal

Name : Manoj Kumar

Designation : Asstt. Engineer

Name & Address of Department/ Office: Gramin Abhiyantran Vibhag, Prakhhand Meerut